

addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent disruption of fuel flow to the engine resulting in failure to attain rated power, power loss in flight, and forced landings, accomplish the following:

(a) For Precision Airmotive Corporation Model MA-3A, MA-3PA, MA-3SPA, and MA4-SPA carburetors:

(1) If not previously accomplished, prior to further flight, inspect the carburetor to determine if a two-piece venturi is installed. Carburetors that have the letter "V" stamped or etched on the lower portion of the data plate, or that have a black, yellow, or blue data plate showing the Precision Airmotive Corporation name and logo, or that have a black Facet A Aerospace Products data plate with a serial number beginning with 750, are already equipped with a one-piece venturi and no further action is necessary provided the engine does not subsequently run rough or experience power loss.

(2) If a two-piece venturi is installed, inspect the carburetor at each annual, 100-hour, or progressive inspection, to determine if the primary venturi is loose or missing. If either of these conditions is found, prior to further flight, repair the carburetor by installing a serviceable two-piece venturi or by installing a one-piece venturi in accordance with Precision Airmotive Service Bulletin (SB) No. MSA-2, Revision 1, dated November 11, 1992, Revision 2, dated December 28, 1993, or Revision 3, dated October 10, 1995. Installing a one-piece venturi constitutes terminating action for the repetitive inspection requirements of this paragraph.

(3) If a one-piece venturi is already installed, or installed in accordance with sub-paragraph (2) of this paragraph, and the engine subsequently runs rough or experiences power loss, accomplish either of the following:

(i) Modify the carburetor in accordance with paragraphs (c), (d) or (e) of this AD, as applicable; or

(ii) Install a carburetor containing a two-piece venturi and resume the repetitive inspections required by paragraph (a)(2) of this AD.

(b) For Precision Airmotive Corporation Model MA-3 series carburetors: at the next annual, 100-hour, or progressive inspection, whichever occurs first, after the effective date of this AD, inspect the carburetor to determine if the primary venturi is loose or missing. If either of these conditions are found, prior to further flight, repair the carburetor by installing a serviceable two-piece venturi, or replace the entire carburetor with a serviceable carburetor. Repeat this inspection at each annual, 100-hour, or progressive inspection.

(c) For Precision Airmotive Corporation Model MA-3SPA series carburetors with Part Numbers (P/N) 10-4894 or 10-4115-1, installed on Teledyne Continental Model O-200A series engines modified on or after the effective date of this AD by installing a one-piece venturi, install a new fuel nozzle in

accordance with Precision Airmotive SB MSA-7, dated September 30, 1994, at the time of installation of the one-piece venturi.

(d) For Precision Airmotive Corporation Model MA-3SPA series carburetors with P/Ns 10-4895, 10-4439, or 10-3237, installed on Teledyne Continental Model O-300 or C-145 series engines modified on or after the effective date of this AD by installing a one-piece venturi, install a new fuel nozzle in accordance with Precision Airmotive SB No. MSA-8, dated July 10, 1995, at the time of installation of the one-piece venturi.

(e) For Precision Airmotive Corporation Model MA-3SPA series carburetors with P/Ns 10-4240, 10-4252, 10-4252-1, or 10-4457, installed on Teledyne Continental Model C-75, C-85, or C-90 series engines modified on or after the effective date of this AD by installing a one-piece venturi, install a new fuel nozzle in accordance with Precision Airmotive SB No. MSA-9, dated October 10, 1995, at the time of installation of the one-piece venturi.

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office. Operators shall submit their requests through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Seattle Aircraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Seattle Aircraft Certification Office.

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the inspection requirements of this AD can be accomplished.

Issued in Burlington, Massachusetts, on July 23, 1997.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 97-20309 Filed 7-31-97; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF COMMERCE

International Trade Administration

19 CFR Part 351

Countervailing Duties

AGENCY: Import Administration, International Trade Administration, Department of Commerce.

ACTION: Notice of public hearing on proposed countervailing duty regulations and announcement of opportunity to file post-hearing comments; correction.

SUMMARY: The Department of Commerce published a document in the **Federal Register** of July 21, 1997, announcing a

public hearing on the proposed countervailing duty regulations. The document contained an incorrect date.

FOR FURTHER INFORMATION CONTACT: Jennifer A. Yeske at (202) 482-0189.

Correction

In document 97-19119 beginning on page 38948 in the issue of Monday, July 21, 1997, make the following correction:

On page 38948, in the third column, under the SUMMARY section "July 31, 1997" should read "August 7, 1997."

Dated: July 24, 1997.

Jeffrey P. Bialos,

Acting Assistant Secretary For Import Administration.

[FR Doc. 97-20284 Filed 7-31-97; 8:45 am]

BILLING CODE 3510-DS-M

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-106043-97]

RIN 1545-AV22

Remedial Amendment Period

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice of proposed rulemaking by cross-reference to temporary regulations.

SUMMARY: In the Rules and Regulations section of this issue of the **Federal Register**, the IRS is issuing temporary regulations relating to the remedial amendment period during which a sponsor of a qualified retirement plan or an employer that maintains a qualified retirement plan can make retroactive amendments to the plan to eliminate certain qualification defects for the entire period. The text of those temporary regulations also serves as the text of these proposed regulations. These proposed regulations will affect sponsors of qualified retirement plans, and employers that maintain qualified retirement plans.

DATES: Written comments and requests for a public hearing must be received by October 30, 1997.

ADDRESSES: Send submissions to: CC:DOM:CORP:R (REG-106043-97), room 5226, Internal Revenue Service, POB 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand delivered between the hours of 8 a.m. and 5 p.m. to: CC:DOM:CORP:R (REG-106043-97), Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue NW, Washington, DC. Alternatively,